



Customer Bulletin

Commercial Products

Rotaries #19-23

August 07, 2025

Missing Information for Telematics Certification

Groundsmaster® 3500-D and 3505-D Series Machines

Bulletin Type Information Only

Affected Units

Model Number(s)	Serial Number(s)
30807	418596746 through 418596754; 418596756 through 418597609; 418596864 through 418596870; 418907381 through 418907547
30849	418914170 through 418914173

Situation Important Information

It was discovered that the telematics certification information (for the Telematics Gateway Lite device that may be equipped on the machine) was not provided with the machine when it was shipped to the distributor.

Corrective Action The telematics certification information is attached to this bulletin. Print this information and include it with the machine documentation.

Safety Awareness Follow reasonable and customary safety precautions.

Parts Not applicable

Parts Retention Not applicable

Warranty Information only, not warrantable

References Find the latest service manuals, diagnostic manuals, schematics, service bulletins and service alerts at [Gateway](#).

Resource	Search Term
Telematics Gateway Lite <i>Addendum</i>	Model and serial number for the machine.



Telematics Gateway Lite

Model No. 122-3876

Form No. 3476-399 Rev A

Addendum

Electromagnetic Compatibility Certification

Domestic: This device complies with FCC Rules Part 15. Operation is subject to the following two conditions: (1) This device may not cause harmful interference and (2) this device must accept any interference that may be received, including interference that may cause undesirable operation.

FCC ID: APV-2630MB

IC: 5843C-2630MB

This equipment has been tested and found to comply within the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Argentina




Australia



European Union



Japan



Malaysia



Morocco

AGREE PAR L'ANRT MAROC

Numéro d'agrément: MR00004658ANRT2024

Date d'agrément: 10/25/2024


New Zealand

R-NZ

South Korea



Taiwan



United Kingdom

