



Customer Service Bulletin Commercial Business Group

REELMASTER® 6500-D and 6700-D

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	03800	50001-70179
	03800TE	70101-70113
	03801	50001-70229
	03801TE	70001-70158
	03802	60001-70234
	03802TE	70001-70160

Subject: Leakage from Input Shaft Seal of Traction Piston Pump.

The traction piston pump in the units listed above may exhibit an oil leak at the input shaft seal within the first 500 hours of operation. A spiral mark on the surface of the shaft may be the cause of the condition. Attempts to correct using a new seal on a shaft with this mark may result in a repeat leak.

If your unit experiences this condition within the first 500 hours of operation, contact your local Toro distributor for an inspection of your unit. Units with this issue will be repaired at no charge.