



Customer Service Bulletin Commercial Business Group

Multi Pro[®] Sprayers

Model/Serial Range:	<u>Model Number:</u>	<u>Serial Number:</u>
	41105	00000-99999
	41101	00000-99999
	3150 Series 5200 (SP)	00000-99999
	3157 Series 5201 (SP)	00000-99999
	3157 Series 5202 (SP 44)	00000-99999
	3157 Series 5210 (MP 44)	00000-99999
	3157 Series 5211 (MP 44)	00000-99999
	3235 Series 5215 (MP 418)	00000-99999
	3235 Series 5218 (MP 418)	00000-99999
	3258 Series 5223 (MP 418)	00000-99999

Subject: Availability of Sub-Assembly to repair Differential failures

A replacement Carrier Assembly that simplifies installation is now available for Differential repairs. The Carrier Assembly is a factory pre-assembled package that provides a quick, reliable repair and avoids the intensive "trial and error" shimming procedures normally required to establish the correct contact pattern between the Ring and Pinion Gears.

Consider using Carrier Assembly (95-9234) when repairing units with a Ring and Pinion or a Differential failure that could be corrected with this assembly. Using this part can reduce the labor cost and down time involved with the repair.

Carrier Assembly (95-9234) is available through your local Toro distributor.