



Customer Service Bulletin Commercial Business Group

Reelmaster® 3100-D

Date: September 29, 2003

Model/Serial Range: **Model Number:**

03201

Serial Numbers:

230000101-230000687

Subject: **Lift intermittently fails to hold, allowing cutting units to fall.**

The Plunger (69-1840) in Control Valve Assembly (95-8581) may have been machined improperly. An improperly machined plunger may intermittently allow the cutting units to drop as soon as the lift handle is released. Should you encounter this issue, please contact your local Toro Distributor for assistance in replacing the plunger.

