



## All Products that Utilize a Drive Coupler Disk Assembly


**Date:** October 30, 2006

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	00000-99999	00001-999999999

### **Subject: Correct Drive Coupler Assembly Installation and Orientation**

During repair of a Toro Product with any Drive Coupler Assembly, the installation orientation of the assembly should be verified for proper installation of coupler and hub; the proper orientation for the Drive Coupler Assembly is at ninety degrees apart.

Incorrect Drive Coupler Installation shown on top picture: The Drive and Driven Coupler are incorrectly installed in-line.



Correct Drive Coupler Installation on the picture below: The Drive and Driven Coupler are installed ninety degrees apart from one another.

