Form No. 3414-560 Rev A

TORO®

Count on it.

Parts Catalog


Lift Handle Kit

MB-1600 Mud Buggy

Model No. 137-0591

Register at www.Toro.com.
Original Instructions (EN)

3414-560 A



Lift Handle Assembly No. 137-0591

Ref.	*Part Number*	*Qty.*	*Description*
1	137-0578-03	1	Pivot
2	137-0568-03	1	Plate-Lever, Foot Control
3	136-4578-03	1	Lever-Control, Valve
4	136-4582-03	1	Guide-Shaft
5	ST81076	1	Pin
6	92-2739	1	Pin-Clevis
7	3272-1	1	Pin-Cotter
8	ST34687	1	Grip-Handle
9	ST32466	2	Bearing
10	321-33	1	Screw-HH
11	3272-11	1	Pin-Cotter
12	104-7201	1	Nut-HF