

PARTS CATALOG

This diagram shows an exploded view of a mechanical assembly. The components are labeled with numbers 1 through 5, with leader lines pointing to their respective parts:

- 1**: Points to a small circular washer or spacer ring.
- 2**: Points to a hex bolt.
- 3**: Points to a hex nut.
- 4**: Points to a small circular washer or spacer ring.
- 5**: Points to a coiled spring.

The assembly includes a main structural plate with a curved section, a long curved arm, and a smaller rectangular plate. The components are shown in their relative positions as they would be assembled.

Ref. No.	Part No.	Description	No. Used
1	3256-24	Washer - Flat	2
2	323-10	Screw - Hex Hd	1
3	32146-2	Nut - Hex Lock	1

Ref. No.	Part No.	Description	No. Used
4	99-8509	Spacer	1
5	E303160	Spring	1