FORM NO. 3322–779

Oil Volume Change

Model No. 20060 and 20061 – 9900001 & UP

ADDENDUM

Mower models 20060 and 20061 require **27 oz. of oil** to fill the crankcase instead of the 20 oz. listed in the Operator's Manual. When adding oil to your mower, add the oil slowly, **checking the level frequently with the dipstick** to ensure that you do not overfill the crankcase. The oil level should be at the FULL mark on the dipstick when finished.

IMPORTANT: Do not overfill the crankcase or serious engine damage will result.

Place this addendum with the Operator's Manual for future reference.

FORM NO. 3322–779

Oil Volume Change

Model No. 20060 and 20061 – 9900001 & UP

ADDENDUM

Mower models 20060 and 20061 require **27 oz. of oil** to fill the crankcase instead of the 20 oz. listed in the Operator's Manual. When adding oil to your mower, add the oil slowly, **checking the level frequently with the dipstick** to ensure that you do not overfill the crankcase. The oil level should be at the FULL mark on the dipstick when finished.

IMPORTANT: Do not overfill the crankcase or serious engine damage will result.

Place this addendum with the Operator's Manual for future reference.