Form No. 3323–324

# 44”Snowthrower

## (For Garden Tractor)

**Model No. 79366—9900001 and Up**

# Parts Catalog

### Ordering Replacement Parts

To order replacement parts, please supply: the part number, the quantity, and the description of each part desired.

### Understanding Reference Numbers

Each identified part in an illustration has a reference number. The reference number for a part also appears in the parts list, along with other information about the part.

This catalog uses two special reference number formats, one to indicate parts in a service assembly and another to indicate the quantity of a given part in an illustration.

#### Service Assembly Reference Numbers

Parts in service assemblies have reference numbers in the form **a:b.** The **a** represents the reference number of the entire service assembly and the **b** represents a sequential number unique to each part within the service assembly.

For example, a wheel assembly might be identified by reference number **6**, the tire by **6:1**, the valve by **6:2**, and the wheel by **6:3**. When you order the assembly identified by reference number 6, you receive all parts identified by reference numbers 6:1, 6:2, and 6:3. However, you may also order any part individually.

Reference numbers of this type appear in illustrations and in part lists.

#### Reference Numbers Indicating Quantity

In an illustration, if a reference number indicates more than one part, the reference number has the form **nX y.** The **n** represents the quantity of the part, the **X** is the multiplication symbol, and the **y** represents the reference number.

For example, in an illustration, the reference number **2X 37** means that two of the parts identified by reference number 37 are indicated.

© The TORO Company — 1999
All Rights Reserved

## Contents


| Description | Page |
|---|---|
| Discharge Chute Assembly | 3 |
| Jack Shaft Assembly | 4 |
| Worm Gear Assembly | 5 |
| Pulley Box Assembly | 6 |
| Crank Assembly | 7 |



## Accessories

| Description | Model / Part No. | Description | Model / Part No. |
|---|---|---|---|

## Part Description Abbreviations

Part descriptions in this catalog may include the following abbreviations.

| Abbreviation | Meaning | Abbreviation | Meaning |
|---|---|---|---|
| AR | as required | INC | incorporated |
| ASM | assembly | LH | left hand |
| CARR | carriage | NI | nylon insert |
| DEG | degrees | PPH | Phillips pan head |
| FH | flat head | PTH | Phillips truss head |
| GA | gauge | PTO | power take off |
| HF | hex flange | RH | right hand |
| HH | hex head | SFH | slotted fillister head |
| HHF | hex head flange | SHH | slotted hex head |
| HLH | hex lag head | SQH | square head |
| HJ | hex jam | SHWH | slotted hex washer head |
| HOC | height-of-cut | SPH | slotted pan head |
| HS | hex socket | SRH | slotted round head |
| HSBH | hex socket button head | STD | standard |
| HSFH | hex socket flat head | TAP | self tapping |
| HSH | hex socket head | TTH | Torx truss head |
| HWH | hex washer head | WH | wing head |
| HWHTF | hex washer head thread forming | | |





Sheet No.:2

# Discharge Chute Assembly

| Ref. No. | Part No. | Qty. | Description |
|---|---|---|---|
| 1 | 3231–2 | 2 | Screw–CARR |
| 2 | 56–2600–01 | 1 | Chute–Upper |
| 3 | 322–2 | 3 | Screw–HH |
| 4 | 26–1110–01 | 1 | Upper Chute Extender |
| 5 | 3230–1 | 3 | Screw–CARR |
| 6 | 12–2040 | 1 | Chute Wire |
| 7 | 27–0220 | 6 | Screw–Special |
| 9 | 25–5450 | 3 | Chute Retainer |
| 10 | 63–2380 | 2 | Decal–Danger |
| 11 | 3296–29 | 37 | Nut–Lock Ni |
| 12 | 322–3 | 24 | Screw–HH |
| 13 | 57–3510–01 | 2 | Plate–Side |
| 14 | 78–0800–01 | 2 | Support–Skid |
| 15 | 3230–2 | 4 | Screw–CARR |
| 16 | 99–2304 | 2 | Blade Support Brkt |
| 17 | 3256–23 | 10 | Washer–Flat |
| 18 | 99–2303–01 | 1 | Blade–Scraper |
| 19 | 95–3866–01 | 1 | Housing–Auger, Wa |
| 20 | 3218–5 | 1 | Nut–Jam |
| 21 | 3233–4 | 1 | Screw–CARR |
| 22 | 3229–25 | 6 | Screw–CARR |
| 23 | 3256–22 | 6 | Washer–Flat |
| 24 | 3296–42 | 6 | Nut–Lock Ni |
| 25 | 92–8652 | 1 | Decal – Warning |
| 26 | 110568 | 1 | Flange Relube–Plain |
| 27 | 3256–28 | 1 | Washer–Flat |

| Ref. No. | Part No. | Qty. | Description |
|---|---|---|---|
| 28 | 3256–26 | 3 | Washer–Flat |
| 29 | 93–1614–01 | 2 | Idler Sprocket |
| 30 | 98–3098 | 1 | Chain – Drive |
| 31 | 119020 | 1 | Flange–Relube Zerk |
| 32 | 909546 | 2 | Screw–Sq. Hd. Set |
| 33 | 95–3867–01 | 1 | Sprocket–38t |
| 34 | 325–7 | 1 | Screw–HH |
| 35 | 110569 | 1 | Bearing & Collar |
| 36 | 6366 | 1 | Key |
| 37 | 92–8748 | 1 | Decal – Attachment |
| 38 | 25–5290–01 | 1 | Ring–Chute Swivel |
| 39 | 3290–326 | 2 | Nut–Push |
| 40 | 3296–39 | 2 | Nut–Lock Ni |
| 41 | 20–4320 | 2 | Washer–Rubber |
| 42 | 94–8079 | 2 | Decal–Danger |
| 43 | 3290–340 | 2 | Belleville Washer |
| 44 | 11–7120–01 | 1 | Deflector Wa |
| 45 | 3296–23 | 1 | Nut–Lock Ni |





Sheet No.:3

# Jack Shaft Assembly

| Ref. No. | Part No. | Qty. | Description |
|---|---|---|---|
| 1 | 95–3999–01 | 2 | Brace ASM. Welded |
| 2 | 95–4023–01 | 2 | Adjuster ASM, Welded |
| 3 | 3256–29 | 2 | Washer–Flat |
| 4 | 32144–1 | 4 | Screw–Taptite |
| 5 | 95–3859–01 | 1 | Pulley Cover ASM, Welded |
| 6 | 6366 | 1 | Key |
| 7 | 95–3836–01 | 1 | Shaft–Jack |
| 8 | 937221 | 1 | Hi Pro Key |
| 9 | 3296–29 | 6 | Nut–Lock Ni |
| 10 | 119020 | 2 | Flange–Relube Zerk |
| 11 | 110569 | 2 | Bearing & Collar |
| 12 | 110568 | 2 | Flange Relube–Plain |
| 13 | 3230–1 | 6 | Screw–CARR |
| 14 | 94–7841 | 1 | Pulley – Driven |
| 15 | 3242–2 | 2 | Screw–Sq. Hd. Set |
| 16 | 3241–5 | 2 | Setscrew |
| 17 | 117338 | 1 | Sprocket–15t |
| 18 | 3253–5 | 6 | Washer–Lock/Sp |
| 19 | 323–4 | 6 | Screw–HH |
| 20 | 99–6455 | 1 | Link–Spring Tension |
| 21 | 95–3848–01 | 1 | Frame ASM, Welded |
| 22 | 98–1640 | 1 | Pin – Clevis |
| 23 | 95–4064 | 2 | Clip – Pin |
| 24 | 9335064 | 4 | Hair Pin Cotter |
| 25 | 100–5022–01 | 1 | Rod–Lift |

| Ref. No. | Part No. | Qty. | Description |
|---|---|---|---|
| 26 | 3256–62 | 3 | Washer–Flat |
| 27 | 94–7671–01 | 1 | Yoke Wa |
| 28 | 98–1639 | 1 | Pin – Clevis |
| 29 | 3256–28 | 2 | Washer–Flat |
| 30 | 95–3993–01 | 1 | Link ASM, Welded |
| 31 | 98–8705 | 1 | Decal – Important |





Sheet No.:4

# Worm Gear Assembly

| Ref. No. | Part No. | Qty. | Description |
|---|---|---|---|
| 1 | 19–8890–01 | 1 | Impeller–Wa |
| 2 | 6–8590 | 1 | Key |
| 3 | 19–8540 | 1 | Impeller Shaft |
| 4 | 3257–23 | 1 | Key–Woodruff |
| 5 | 237–87 | 1 | Quad Ring |
| 6 | 20–3210 | 1 | Bushing–Special |
| 7 | 252–78 | 1 | Bearing–Thrust |
| 8 | 252–76 | 1 | Bearing–Thrust |
| 9 | 252–77 | 1 | Thrust–Washer |
| 10 | 5–7170 | 1 | Gear |
| 11 | 5–7180 | 1 | Gear–Worm 21t |
| 12 | 252–71 | 2 | Bearing–Thrust |
| 13 | 37–8860 | 1 | LH Gear Case/Bshg ASM |
| 13:1 | 256–237 | 1 | Bushing |
| 13:3 | 7–0045 | 1 | Oil Seal |
| 14 | 281–1 | 1 | Plug–SQH Pipe |
| 15 | 3–8664 | 1 | Washer–Thrust |
| 16 | 5210 | 1 | Washer–Shim |
| 17 | 32120–72 | 1 | Ring–Ext Snap |
| 18 | 256–32 | 1 | Bushing |
| 19 | 57–3300–01 | 1 | Auger Wa 44”,Right |
| 20 | 57–3370–01 | 1 | Auger Wa 44”,Left |
| 21 | 321–4 | 8 | Screw–HH |
| 22 | 3256–22 | 8 | Washer–Flat |
| 23 | 20–0990 | 2 | Flange–Bearing, Front |

| Ref. No. | Part No. | Qty. | Description |
|---|---|---|---|
| 24 | 20–0980 | 2 | Bearing |
| 25 | 20–1000 | 2 | Flange–Bearing, Rear |
| 26 | 3296–42 | 8 | Nut–Lock Ni |
| 27 | 3235–22 | 2 | Screw–HH |
| 28 | 2844 | 2 | Washer |
| 29 | 322–14 | 2 | Screw–HH |
| 30 | 3296–29 | 2 | Nut–Lock Ni |
| 31 | 3257–33 | 2 | Key–Woodruff |
| 32 | 57–3500 | 1 | Auger Shaft |
| 33 | 37–8850 | 1 | RH Gear Case/Bshg ASM |
| 33:1 | 256–237 | 1 | Bushing |
| 33:3 | 7–0045 | 1 | Oil Seal |
| 34 | 32144–41 | 8 | Screw–Taptite |
| 35 | 92–9839 | 1 | Gasket–Gear Box |
| 36 | 3242–6 | 2 | Screw–Sq Hd Set |





Sheet No.:5

# Pulley Box Assembly

| Ref. No. | Part No. | Qty. | Description |
|---|---|---|---|
| 1 | 100–4164 | 1 | V–Belt–Two Stage Snow |
| 2 | 94–2447 | 4 | Pulley – Idler |
| 3 | 32146–2 | 4 | Nut–Lock Ni |
| 4 | 95–3984–01 | 2 | Cover–Belt |
| 5 | 32144–70 | 1 | Screw–HH |
| 6 | 94–7686–01 | 1 | ASM–Pivot Rod |
| 7 | 95–3850–01 | 1 | Pulley Box ASM |
| 8 | 3296–29 | 2 | Nut–Lock Ni |
| 10 | 99–6452–01 | 1 | Lever, Wa |
| 11 | 99–6453 | 1 | Shoulder Bolt |
| 12 | 99–6456 | 1 | Spring–Ext |
| 13 | 323–8 | 2 | Screw–HH |
| 14 | 302–5 | 1 | Fitting–Lube |
| 15 | 95–3851–01 | 1 | Lever–Idler, Wa |
| 16 | 9335044 | 2 | Hairpin Cotter |
| 17 | 99–6884 | 2 | Pin |
| 18 | 99–6454 | 1 | Bracket–Pivot |
| 19 | 322–3 | 1 | Screw–HH |

| Ref. No. | Part No. | Qty. | Description |
|---|---|---|---|




Sheet No.:6

# Crank Assembly

| Ref. No. | Part No. | Qty. | Description |
|---|---|---|---|
| 1 | 99–6885 | 1 | Nut–Push |
| 2 | 40–8230 | 1 | Chute Control Grip |
| 3 | 98–3090 | 1 | Rod – Chute Control |
| 4 | 95–3864–01 | 1 | Tube–Crank Support |
| 5 | 283–66 | 1 | Clevis Pin |
| 6 | 94–2686 | 1 | ASM – Universal Joint |
| 7 | 32121–47 | 1 | Pin – Roll |
| 8 | 9335054 | 1 | Pin–Hair Cotter |
| 9 | 8–8600 | 1 | Chuteworm Gear |
| 10 | 32121–50 | 1 | Pin–Spring |
| 11 | 3290–212 | 1 | Washer–Spring |
| 12 | 3230–2 | 2 | Screw–CARR |
| 13 | 98–3089–01 | 1 | Bracket–Gear |
| 14 | 3256–24 | 3 | Washer–Flat |
| 15 | 92–7046 | 1 | Rod (Plated) |
| 16 | 3272–10 | 1 | Pin–Cotter |
| 17 | 98–3094–01 | 1 | Crank Support, Lower |
| 18 | 3256–23 | 1 | Washer–Flat |
| 19 | 3296–29 | 2 | Nut–Lock Ni |
| 20 | 323–6 | 2 | Screw–HH |
| 21 | 3253–21 | 2 | Washer–Lock/Sp |
| 22 | 3290–238 | 1 | Washer–Pyramidal Lock |
| 23 | 9335044 | 1 | Hairpin Cotter |

| Ref. No. | Part No. | Qty. | Description |
|---|---|---|---|


TORO®