Form No. 3447-172 Rev A

TORO®

Count on it.

Parts Catalog


Pole Saw Attachment

Flex-Force Power System™ 60V MAX Attachment

Model No. 88714—Serial No. 322000001 and Up

Register at www.Toro.com.
Original Instructions (EN)

3447-172 A



Pole Saw Attachment Assembly

Ref.	*Part Number*	*Qty.*	*Description*
1	88619	1	Bar
2	88621	1	Chain
3	139-5378	1	Sleeve-Bar
4		1	Head ●
5	145-4877	1	Oil Cap
6	145-4879	1	Cover-Gear, Driver

● Not serviced separately

Attachments and Accessories

For 88714 Pole Saw Attachment Flex-Force Power System 60V MAX Attachment

Product Name	Model/Part
60V Battery Charger 2 AMP	88602
60V Rapid Battery Charger 5.4 AMP	88605
60V Battery Charger 1 AMP	88610
60V 2.0 AH Battery	88620
60V LI-ION Battery 2.5 AH	88625
60V LI-ION, Battery 4.0 AH	88640
60V LI-ION Battery 5.0 AH	88650
60V LI-ION Battery 6.0 AH	88660
60V LI-ION Battery 7.5 AH	88675



Count on it.