Form No. 3440-131 Rev B

TORO®

Count on it.

Parts Catalog

Flex-Force Power System™

41cm (16in) 60V MAX Chainsaw

Model No. 51851—Serial No. 320000001 and Up

Register at www.Toro.com.
Original Instructions (EN)

3440-131 B

Ordering Replacement Parts

To order replacement parts, please supply the part number, the quantity, and the description of each part desired.

Understanding Reference Numbers

Each identified part in an illustration has a reference number. The reference number for a part also appears in the parts list, along with other information about the part.

This catalog uses two special reference number formats, one to indicate parts in a service assembly and another to indicate the quantity of a given part in an illustration.

Service Assembly Reference Numbers

Parts in service assemblies have reference numbers in the form a:b. The a represents the reference number of the entire service assembly and the b represents a sequential number unique to each part within the service assembly.

For example, a wheel assembly might be identified by reference number 6, the tire by 6:1, the valve by 6:2, and the wheel by 6:3. When you order the assembly identified by reference number 6, you receive all parts identified by reference numbers 6:1,6:2, and 6:3. However, you may also order any part individually. Reference numbers of this type appear in illustration and in parts lists.

Reference Numbers Indicating Quantity

In an illustration, if a reference number indicates more than one part, the reference number has the form nX y. The n represents the quantity of the part, the X is the multiplication symbol, and the y represents the reference number.

For example, in an illustration, the reference number 2X 37 means that two of the parts identified by reference number 37 are indicated.


Contents

16in Cordless Chainsaw Assembly 4
Attachments and Accessories 6

© 2022—The Toro® Company
8111 Lyndale Avenue South
Bloomington, MN 55420

Contact us at www.Toro.com.
Printed in the USA.
All Rights Reserved

16in Cordless Chainsaw Assembly



16in Cordless Chainsaw Assembly (continued)

Ref.	Part Number	Qty.	Description
1	140-8407	1	Adjuster Bar Bracket ASM
2	140-8406	1	Drive Gear ASM
3	140-8403	1	Oil Cap ASM
4	140-8404	1	Handle ASM
5	140-8405	1	Chain Brake ASM
6	140-8413	1	Bar Cover ASM
7	140-8440	1	Bar Cover Support Bracket ASM
8	140-8414	1	Oil Pump ASM
9	140-8443	1	Bar-Sleeve, Chainsaw
10	140-8444	1	Tool-Adjustment, Bar
12	88613	1	Bar-Replacement
13	88614	1	Chain
14	88620	1	Battery-60V 2.0Ah
15	88610	1	Charger-Battery, 60V 1 Amp

Attachments and Accessories

For 51851 Flex-Force Power System 41cm (16in) 60V MAX Chainsaw

Product Name	Model/Part
Toro Premium Bar and Chain Oil (1 Qt Bottle)	38914
Toro Premium Bar and Chain Oil (1 Gal)	38917
60V Battery Charger 2 AMP	88602
60V Rapid Battery Charger 5.4 AMP	88605
60V Battery Charger 1 AMP	88610
Replacement Bar	88613
Chain-16in	88614
60V 2.0 AH Battery	88620
60V LI-ION Battery 2.5 AH	88625
60V LI-ION, Battery 4.0 AH	88640
60V LI-ION Battery 6.0 AH	88660
60V LI-ION Battery 7.5 AH	88675

Notes:



Count on it.