Form No. 3462-809 Rev A

TORO®

Count on it.

Parts Catalog

Upper Receiver Replacement Kit


Greensmaster® 1018, Flex™ 1018, 1021, e1021, Flex™ 1021, or 1026 Mower

Model No. 147-2288

Register at www.Toro.com.
Original Instructions (EN)

CE

3462-809 A



Upper Receiver Assembly No. 147-2288

Ref.	*Part Number*	*Qty.*	*Description*
1	147-2284-0P	1	Upper Receiver, Welded
2	147-2269	1	Cam-Handle, Pivot
3	119-4040	1	Nut-HF, NI
4	283-61	1	Pin-Yoke
5	116-6639	1	Pin-Cotter, Locking
6	1-808285	1	Pin-Clevis
7	140-9312	1	Pin-Cotter, Locking