Form No. 3477-603 Rev C

TORO®

Count on it.

Parts Catalog

HoverPro® 550 Machine

Model No. 02617—Serial No. 420000000 and Up

Register at www.Toro.com.
Original Instructions (EN)

CE

3477-603 C

Ordering Replacement Parts

To order replacement parts, please supply the part number, the quantity, and the description of each part desired.

Understanding Reference Numbers

Each identified part in an illustration has a reference number. The reference number for a part also appears in the parts list, along with other information about the part.

This catalog uses two special reference number formats, one to indicate parts in a service assembly and another to indicate the quantity of a given part in an illustration.

Service Assembly Reference Numbers

Parts in service assemblies have reference numbers in the form a:b. The a represents the reference number of the entire service assembly and the b represents a sequential number unique to each part within the service assembly.

For example, a wheel assembly might be identified by reference number 6, the tire by 6:1, the valve by 6:2, and the wheel by 6:3. When you order the assembly identified by reference number 6, you receive all parts identified by reference numbers 6:1,6:2, and 6:3. However, you may also order any part individually. Reference numbers of this type appear in illustration and in parts lists.

Reference Numbers Indicating Quantity

In an illustration, if a reference number indicates more than one part, the reference number has the form nX y. The n represents the quantity of the part, the X is the multiplication symbol, and the y represents the reference number.

For example, in an illustration, the reference number 2X 37 means that two of the parts identified by reference number 37 are indicated.


Contents

Cutting Assembly 4
Engine and Deck Assembly 6
Handle Assembly 8
Attachments and Accessories 10

© 2026—The Toro® Company
8111 Lyndale Avenue South
Bloomington, MN 55420

Contact us at www.Toro.com.
Printed in the USA.
All Rights Reserved


Cutting Assembly



Cutting Assembly (continued)

Ref.	Part Number	Qty.	Description
8	H190210	1	Spanner
9	H192025	3	Spacer-Blade, Aluminium
10	H192270	1	Spacer-Distance
12	H192272	1	Retainer-Blade
13	134-8686	1	Blade, 53 CM
14	H292018	1	Screw-Set


Engine and Deck Assembly



Engine and Deck Assembly (continued)

Ref.	Part Number	Qty.	Description
13	111-2157	4	Screw-Taptite
15	134-6432	1	Engine-Honda (Gcvx170)
17	1662	1	Key-Woodruff
18	H190118	1	Protector-Seal, Oil
21	H290011	1	Drive And Spacer ASM
21:2	09479	1	Washer-Plain
22	H192268	1	Impeller
23	111-6004	1	Deck ASM
23:4	111-5393	1	Decal-Warning
23:5	111-9826	1	Decal-Danger
23:6	H292280	2	Insert
24	H290003	1	Frame-Engine
24:2	H192266	8	Insert-Brass
25	H292004	8	Screw-Pozi Pan
26	H292269	1	Bracket
28	H292279	2	Screw
33	111-5351	1	Decal-Hover Pro
35	111-9826	1	Decal-Danger

Handle Assembly



Handle Assembly (continued)

Ref.	Part Number	Qty.	Description
3	09438	1	Nut-Nyloc
6	162-1328	8	Washer-Plain
11	134-6958	1	OPC Cable
16	H192204	2	Handwheel
17	H290237	1	Handle-Upper
18	H290239	1	Arm-Bail
19	H290286	1	Footstop
20	111-7260-03	1	Handle-Lower
21	H292026	2	Bolt-U
22	H292058	4	Spacer-Handle
24	H292276	2	Grip-Handle
25	162-1331	2	Pin-Clevis ASM
26	HY3966	2	Tie-Cable
27	H295159	1	Decal-Stop
29	05010	1	Bolt
30	137-3088	1	Nut-Hex

Attachments and Accessories

For 02617 — HoverPro 550 Machine

Product Name	Model/Part
Transport Wheel Kit	02622
Handlebar Extension Kit	02628

Notes:



Count on it.