Form No. 3360-604 Rev A

Solid Windshield Kit

for Workman® MD, MDX, MDE Utility Vehicle

Model No. 07325

Installation Instructions

Note: Determine the left and right sides of the machine from the normal operating position.

Note: To attach the Solid Windshield Kit, you must have a Canopy Kit (07324) installed on your vehicle.

Installation

Loose Parts

Use the chart below to verify that all parts have been shipped.

Description	Qty.	Use
Windshield, solid	1	Install the windshield kit.
Snap on clip, windshield (10 inch)	7	
Windshield tube	1	
Bolt (1/4 x 1-1/4 inch)	2	
Flat washer (1/4 inch)	2	
Capped nut(1/4 inch)	2	

© 2008—The Toro® Company
8111 Lyndale Avenue South
Bloomington, MN 55420

Register at www.Toro.com.

CE

Original Instructions (EN)
Printed in the USA.
All Rights Reserved




Figure 1

1. Windshield
2. Snap-on clip
3. Windshield tube
4. Capped nut
5. Canopy frame
6. Bolt and flat washer

1. Position the machine on a level surface. Set the parking brake, turn the ignition off, and remove the key.

If you leave the key in the ignition switch, someone could accidently start the engine and seriously injure you or other bystanders.

Remove the key from the ignition switch before you do any maintenance.

2. Attach the windshield tube to the front support tubes on the canopy using two bolts (1/4 x 1-1/4 inch), two flat washers, and two capped nuts (Figure 1).
3. Remove the protective film from the windshield.
4. Install the snap-on clips to windshield as shown in Figure 1.
5. Attach the snap-on clips on the side of the windshield to the canopy frame. Align the clips on the bottom of the windshield with the windshield tube and press the windshield securely into place (Figure 1).
6. Ensure that all of the clips are secured firmly to the frame.

Maintenance

Remove the solid windshield before transporting the vehicle on a trailer.

Important: To prevent degrading of the windshield or clips, clean the windshield with mild soap and water only. Do not use glass cleaners and solvents such as ammonia, alcohol, and petroleum distillates.