FORM NO. 3316–217Rev. A


TORO®

MODEL NO. 07301

PARTS CATALOG

FULL AREA FLATBED KIT

For Workman 3000 Series



FULL AREA FLATBED ASSEMBLY

Ref. No.	Part No.	Description	No. Used
1	3296–2	Nut – Lock	4
2	92–1233	Pin – Clevis	4
3	92–1298	Pin – Lynch	8
4	32148–6	Insert – Threaded	4
5		Bed	1
6	323–42	Screw – Cap Hex. Hd.	4
†6	323–42	Screw – Cap Hex. Hd.	6
7	92–1278	Plate – Flatbed	4
†8	92–1279	Plate – Bed Pivot	4
†9	92–1208	Spacer – Pivot Plate	2


Ref. No.	Part No.	Description	No. Used
10	3296–44	Nut – Lock	4
†10	3296–44	Nut – Lock	6
11	92–1312	Decal – Warning	2
†12	92–5950	Block – Spacer	2
†13	3250–30	Screw – Pan Hd.	4
14	32122–28	Screw – Truss Hd.	4
15	92–1321	Block – Spacer	2
16	42–6200	Shim – Cushion	4
17	32148–7	Insert – Threaded	4

*Not Illustrated

†Used on Workman 3300D Only

© The TORO Company –1993
All Rights Reserved

TPS



T–1565

RADIATOR COVER ASSEMBLY

Ref. No.	Part No.	Description	No. Used
1	74–5950	Latch – Swell	2
2	92–1307	Cover – Radiator	1
3	92–1313	Bracket – Cover LH	1
4	322–2	Screw – Cap Hex. Hd.	4

Ref. No.	Part No.	Description	No. Used
5	3296–29	Nut – Lock	4
6	92–1314	Bracket – Cover RH	1
7	3256–23	Washer – Flat	4

Litho in U.S.A.