Form Number 3361-205 Rev A

# Replacement Idler Kit
## ProCore® Processor

**Model No. 110-2726**

# Parts Catalog

**Ordering Replacement Parts**

To order replacement parts, please supply the part number, the quantity, and the description of each part desired.

**Understanding Reference Numbers**

Each Identified part in an illustration has a reference number. The reference number for a part also appears in the parts list, along with other information about the part.

This catalog uses two special reference number formats, one to indicate parts in a service assembly and another to indicate the quantity of a given part in an illustration.

**Service Assembly Reference Numbers**

Parts in service assemblies have reference numbers in the form a:b. The a represents the reference number of the entire service assembly and the b represents a sequential number unique to each part within the service assembly.

For example, a wheel assembly might be identified by reference number 6, the tire by 6:1, the valve by 6:2, and the wheel by 6:3. When you order the assembly identified by reference number 6, you receive all parts identified by reference numbers 6:1, 6:2, and 6:3. However, you may also order any part individually. Reference numbers of this type appear in illustrations and in part lists.


**Reference Numbers Indicating Quantity**

In an illustration, if a reference number indicates more than one part, the reference number has the form nX y. The n represents the quantity of the part, the X is the multiplication symbol, and the y represents the reference number.

For example, in an illustration, the reference number 2X 37 means that two of the parts identified by reference number 37 are indicated.

© The Toro Company - 2008
All Rights Reserved

Register your product at www.Toro.com




# Replacement Idler Kit Assembly No. 110-2726

| Ref | Part No. | Qty. | Description |
|---|---|---|---|
| 1 | 110-2717 | 1 | Arm-Idler, ASM |
| 1:2 | 256-132 | 2 | Bushing-Flange |
| 1:3 | 302-19 | 1 | Fitting-Grease |
| 2 | 110-2710-03 | 1 | Pivot-Idler |
| 3 | 3-8514 | 1 | Washer-Thrust |
| 4 | 32151-36 | 1 | Ring-Retaining |
| 5 | 104-8301 | 1 | Nut-Flange, NI |
| 6 | 80-6990 | 2 | Washer-Hardened |
| 7 | 325-9 | 4 | Screw-HH |
| 8 | 3217-7 | 1 | Nut-Hex |
| 9 | 94-2547 | 1 | Bolt-Eye |
| 10 | 54-2730 | 1 | Spring-Extension |
| 11 | 3233-7 | 1 | Screw-CARR |