FORM NO. 3317–372


TORO®

PART NO. 87–9960

PARTS CATALOG

MPH TACHOMETER KIT

For Workman 3100




T–1813

TACHOMETER KIT ASSEMBLY

Ref. No.	Part No.	Description	No. Used
1	321–4	Screw – Cap Hex. Hd.	2
2	87–8280	Plate – Mag. Pick–Up	1
3	32128–33	Nut – Flange Hd.	2
4	87–9920	Tachometer Assembly (MPH)	1
5	3220–7	Nut – Hex.	1
6	87–7590	Mount – Mag. Pick–Up	1

Ref. No.	Part No.	Description	No. Used
7	75–6700	Sensor – Magnetic (Incl. Ref. #5)	1
8	3296–29	Nut – Lock	2
9	3230–3	Bolt – Carriage	2
*	3290–378	Tie – Cable	2

© The TORO Company – 1994
All Rights Reserved



T–1677

TACHOMETER SERVICE ASSEMBLY

Ref. No.	Part No.	Description	No. Used
1	87–9920	Tachometer Assembly (MPH) (Incl. Ref. #1–6)	1
2	219–17	Bulb	1
3	87–6270	Assembly – Socket & Bulb (Incl. Ref. #2)	1
4	3217–25	Nut – Hex.	2
5	3217–29	Nut – Hex.	4
6		Clamp – Tachometer	1

Litho In USA