FORM NO. 3316−818 Rev. A


TORO®

MODEL NO. 07341

PARTS CATALOG

1/3 AREA FLATBED KIT

For Workman 3000 Series



T−1549−2

1/3 AREA FLATBED ASSEMBLY

Ref. No.	Part No.	Description	No. Used
1		1/3 Flatbed Assembly	1
2	92−9028	Cover Assembly	1

Ref. No.	Part No.	Description	No. Used
3	3234−1	Screw − Hex. Flange Hd.	4

TPS

© The TORO Company − 1996