Form No. 3372-846 Rev A

TORO®

Count on it.

Parts Catalog

Valve Replacement Kit


2010-2011 Multi-Pro® 5800 Turf Sprayer

Model No. 121-5049

CE

Register at www.Toro.com.

Original Instructions (EN)



Valve Replacement Kit No. 121-5049

Ref.	*Part Number*	*Qty.*	*Description*
1	121-5011	1	Bracket-Loom, 4 Hose
2	121-5012	1	Bracket-Loom, 4 Hose
3	121-5054	3	Piston ASM
3:1	121-5057	2	O-Ring, Arag Valve Piston
4	121-5055	3	Seat-Valve ASM
4:1	119-4868	1	O-Ring
4:2	119-4862	1	Fork
5	108-3723	4	Grommet
6	3234-33	2	Screw-HHF
7	104-7201	2	Nut-HF
8	3234-47	2	Screw-HHF
9	104-8300	2	Nut-Flange, NI
10	3290-379	2	Tie-Cable