
FORM NO. 3319–283

TORO®

PART NO. 95–3263

PARTS CATALOG

# WIRE HARNESS KIT
## For Groundsmaster® 3000 Series




T–2630–2


## WIRE HARNESS ASSEMBLY

| Ref. No. | Part No. | Description | No. Used |
|---|---|---|---|
| 1 | 95–1596 | Harness – Wire | 1 |
| 2 | 3290–378 | Tie – Cable | 3 |
| 3 | 95–0690 | Pad – Mounting | 3 |

| Ref. No. | Part No. | Description | No. Used |
|---|---|---|---|
| 4 | 95–5122 | Switch – Toggle | 2 |
| 5 | 95–7021 | Decal – Switch | 1 |

© The TORO Company – 1996
*All Rights Reserved*

TPS




CIRCUIT MADE

| | |
|---|---|
| KEYWAY | 2–4; 5–1 |
| CENTER | OFF |
| OPPOSITE | 2–1; 5–4 |

T–2631–1

# ELECTRICAL SCHEMATIC

| Ref. No. | Part No. | Description | No. Used |
|---|---|---|---|
| 1 | 218–573 | Fuse – 5 Amp | 2 |
| * | 95–3287 | Fuse | 1 |

| Ref. No. | Part No. | Description | No. Used |
|---|---|---|---|

*Not Illustrated