




Form No. 3382-601 Rev A

Count on it.

Parts Catalog

Actuator Service Assembly Kit **Rotary Broom 30743 for Groundsmaster®** **300 Series** Model No. 127-6509





Actuator Assembly

Ref.	Part Number	Qty.	Description
2	86-1990	3	Washer-Thrust
3	325-18	1	Screw-HH
4	99-5107	1	Nut-Lock
5	23-2270	3	Bushing-Rubber
6	127-6508-03	1	Hub
7	3256-14	4	Washer-Flat
8	3290-424	4	Screw-SHH