Form No. 3395-943 Rev A

TORO®

Count on it.

Parts Catalog

Cam Sensor Improvements Kit


4045 Directional Drill

Model No. 132-4165

Register at www.Toro.com.
Original Instructions (EN)

CE

3395-943 A



Cam Sensor Improvement Assembly No. 132-4165

Ref.	*Part Number*	*Qty.*	*Description*
1	132-4172-03	1	Bracket-Loader, Rod
2	81-0130	2	Nut-Flange, NI
3	132-4173-03	1	Plate-Sensor
4	33103-016	2	Screw-HHF
5	112-8617	2	Nut-Hex
6	33095-00	2	Washer-Flat
7	132-4180	1	Screw-Cap, HH
8	60-6500	4	Screw-HH
9	131-0177	2	Sensor-Rotary
10	127-2018	4	Nut-HHF
11	132-4171-03	1	Bracket-Sensor, Cam

Ref.	*Part Number*	*Qty.*	*Description*
12	115-1115	2	Nut-Lock, HHF
13	33106-060	2	Screw-HHF
14	3272-30	2	Pin-Cotter
15	131-7628	1	Gasket-Control ●
16	122-0673	2	Harness-Adaptor, Sensor
17	122-0677	1	Cap
18	3-8514	1	Washer-Thrust
19	01-168-1614	1	Bushing
20	104-3082	1	Nut-Lock, HHF
41	32180-011	1	Clip-Connector
42	3290-378	3	Tie-Cable

● Not illustrated