



Customer Service Bulletin Commercial Business Group

Multi Pro[®] 1200 and 1250

Date: May 10, 2004

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	41163	240000101-240000324
	41164	240000101-240000246
	41165	240000101-240000108

Subject: The Bracket for the Spray Gun may not fit-up to the front tank strap.

Early units produced in 2004 may not have a square hole in the front Tank Strap (106-5063-03) which is necessary to mount the Spray Gun Bracket from the Spray Gun Kit (41133). The square hole is only necessary when mounting the Spray Gun Kit.

Installing a Spray Gun Kit (41133) to one of the units listed will require the front Tank Strap (106-5063-03) be replaced. The part has been changed to include the necessary holes. Refer to the figure below for Hanger and Tank Strap orientation. Contact your Toro distributor should you encounter this situation and are going to mount the Spray Gun Bracket.




Figure 2

- 1. Front tank strap
- 2. Hose hook, single bend
- 3. Spray gun bracket