



**Important Safety Notice to all Z Master 100 Series Compact ZRT owners's**

Affected Models include:

Model Numbers:

74170  
74171  
74172  
74173  
74174  
74175  
74176  
74177  
74178  
74179  
74197  
74198

Serial Numbers:

990001-200999999  
990001-200999999  
990001-200999999  
990001-200999999  
990001-200999999  
990001-200999999  
210000001-220000263  
210000001-220000388  
210000001-220000313  
210000001-220000389  
210000001-220000114  
210000001-220000327

If you are the owner of one or more **Toro Z Master 100 Series Compact ZRT commercial mowers** as outlined above, your mower is affected by a **MANDATORY SAFETY REWORK** campaign to install a newly designed crossover tail pipe extension.

In voluntary cooperation with the U.S. Consumer Product Safety Commission, Toro is recalling Z Master 100 Series Compact ZRT commercial mowers. **Failure to update your unit could expose the operator and/or bystanders to the risk of fire and serious personal injury. Do not use your unit until this rework has been completed.**

**ISSUE:** In an ongoing effort to identify potential ignition sources of fuel vapors, we have determined that an "after bang" or "backfire" which might occur during operation or at shutdown of the engine can ignite fuel vapors.

**WHAT TO DO: Stop** using your mower immediately. The rework will consist of replacing the existing spark arrester with a new crossover tail pipe. The dealer will also inspect and if necessary will replace any fuel tank grommets that shows signs of leakage, seepage or weather cracking. **A free set of blades will be given to each registered customer upon completion of the rework. Warranty will cover the parts and labor cost associated with this campaign.**

Please note that pick-up and delivery allowances have been made for homeowners who cannot transport their unit to their local dealer. Please contact the dealer that you purchased your unit from to schedule an appointment to get your mower reworked. The necessary parts have most likely already been sent to the dealer where you purchased your unit.

All of us here at Toro appreciate your patronage and your use of our products. We apologize for any inconvenience that this rework may cause you. If you have any questions regarding this matter, please feel free to contact Toro's customer service department at **1-800-348-2424**.