


CPSC, The Toro Company Announce Recall of Power Sweep Electric Blowers™

In cooperation with the U.S. Consumer Product Safety Commission (CPSC), The Toro Company, Bloomington, Minn., is voluntarily recalling certain model and year 2000, 2001, and 2002 Power Sweep Electric Blowers™. The model and serial number are located on a sticker on the left hand side of the blower housing.



A. Black - NOT OK

B. Beige - OK

Only units with a **BLACK** impeller/fan within these serial number ranges are affected.

If your unit has a **BEIGE** impeller/fan, it is OK.

Model Numbers	Serial Numbers
51586	000055100-000058581
51586	200000001-200365313
51586	210000001-210284435
51586	220000001-220255609

Problem:

The impeller (fan for moving the air) in certain 2000-2002 Toro Power Sweep Electric Blowers may break and pieces may be ejected, presenting a risk of thrown object injury to the operator or bystanders. Only units listed above with a black impeller/fan are affected. Any units with an impeller/fan that is not black are not affected by the recall.

What to do:

If your Power Sweep Electric Blower has a black impeller/fan stop using the blower immediately. To obtain instructions on how to receive a replacement Power Sweep Electric Blower click on the following link: [Power Sweep Electric Blower Recall Instructions](#). If you need further assistance you may contact us by phone (888-279-3191). You will need to provide your model, serial number, and home address.