



Greensmaster®/TriFlex® Replacement Seats

Product: Greensmaster and Triflex Traction Units

June 6, 2019

Affected Units:	Models:	Serial Numbers:
Greensmaster 3150	04357	220000001-311999999
Greensmaster 3150	04358	312000001-403410000
Greensmaster 3250	04383	200000001-311999999
Greensmaster 3250-D	04384	312000001-403410000
Greensmaster 3300	04510	311000001-403070000
Greensmaster 3400	04520	311000001-403342000
Greensmaster 3320	04530	311000001-403343000
Greensmaster 3420	04540	311000001-403421000

Situation: Toro has changed the seats for the Greensmaster and TriFlex product lines and obsoleted the previous replacement seat offerings P/N 104-4620. The new replacement seat requires a new seat base to be installed when a seat replacement is required.

Action Required: When original seat P/N 104-4620 is replaced, the new corresponding seat base or hardware must also be used as shown in the fitment guide **Table 1**. Models outside this bulletin or above serial ranges listed require no special actions.

Model Number	New Seat Model / Part Number	Seat Installation Kit P/N	Optional Armrest Kits	Description
04510 04520 04530 04540	04508	139-6479	126-2058 121-3660 121-3658	LH & RH Armrest kit LH Only Armrest kit RH Only Armrest kit
04384	139-2680	121-1759 (qty 4) *	126-2058 121-3660 121-3658	LH & RH Armrest kit LH Only Armrest kit RH Only Armrest kit
04358	139-2680	Not Required	126-2058 121-3660 121-3658	LH & RH Armrest kit LH Only Armrest kit RH Only Armrest kit

Table 1

**Spacers need to be installed between seat frame and adjuster slides*