

September 05, 2019

Legacy Groomer Drive Shaft and Pulley Service Kits

Groomer Drive System

Bulletin Type Information Only

Status Final Release

Affected Units

Affected Units	Model Number(s)	Serial Number(s)
Groomer Drive System	04259	All
Groomer Drive System	04260	All
DPA Reel Mower Groomer	04709	All
DPA Reel Mower Groomer	04710	All

Situation Important Information

Toro has discontinued the production of the following Groomer Drive Kit model numbers: 04259, 04260, 04709, and 04710

Corrective Action Due to the discontinued production of Groomer Drive Kit models 04259, 04260, 04709, and 04710, Toro has created **Legacy Groomer Drive Shaft and Pulley Service Kits**. These kits allow the distributor and customer to continue servicing their existing groomer drive kits when repairs are needed.

If drive and/or pulley replacement parts are required on the discontinued Groomer Drive Kit models, please refer to Table 1, Table 2, or Table 3. When you order replacement parts, you may notice that certain part numbers are obsolete or that no replacement parts are available, as inventory is depleted. When this situation arises, inform distribution parts channels, customers, and sales staff of the new service kits indicated in the following tables:

Table 1 (Obsolete Part No. 117-6794 and 120-3230)

Model	Part Number	Description
04259	139-2696	Groomer Kit
04260	139-2709	Groomer Shaft Assembly
04709	138-9702	Groomer Kit
04710	139-2697	Groomer Kit

Table 2 (Obsolete Part No. 117-6795)

Model	Part Number	Description
04259	139-2696 & 139-2698	Groomer Kit and Blades Kit
04260	139-2711	Grooming Reel
04709	138-9702 & 139-2698	Groomer Kit and Blades Kit
04710	139-2697 & 139-2698	Groomer Kit and Blades Kit

Table 3 (Obsolete Part No. 117-6799)

Model	Part Number	Description
04259	139-2696 & 139-2699	Groomer Kit and Blades Kit
04260	139-2709	Grooming Reel Assembly
04709	138-9702 & 139-2699	Groomer Kit and Blades Kit
04710	139-2697 & 139-2699	Groomer Kit and Blades Kit

Warranty

Information only, not warrantable