



Count on it.


Parts Catalog

**GeoLink® GSM Precision Spray
System Kit**

Multi Pro® 1750 or 5800 Turf Sprayer

Model No. 41343—Serial No. 32000000 and Up






MP5800 GeoLink GSM Precision Spray System Assembly

Ref.	Part Number	Qty.	Description	Ref.	Part Number	Qty.	Description
1	130-7306	1	Reciever	5	122-1649	1	Harness-Wire, Adapter
2	133-0410	1	Control Console ASM	6	122-1650	1	Harness-Wire,Adptr
2:1	131-3797	1	Arm-Mount, Ram ●	6:5	32180-089	1	Cap-Plug, 3 Way
2:2	130-7299	1	Base-Mount, Ram ●	7	138-6288	1	Modem CI55-Lte Aus
3	137-4258	1	Controller - Rate/Auto-Section, Asc-10	8	139-6148	1	Antenna ASM, CI55
4	122-1373	1	Harness-Wire, Geolink	9	138-6284	1	Harness - Console To Modem, CI-55
4:2	32180-043	2	Resistor-120 Ohm	10	138-6285	1	Harness - Modem To Power, CI-55
4:3	218-578	1	Fuse-Blade, 10 Amp	11	140-7310	1	Kit - Imu + Rtk Unlock
4:4	32180-019	1	Cover-Fuse, Single	11:1	130-7329	1	Module-Imu
4:5	122-1404	2	Terminator-Isobus				

● Obtain parts from Toro® NSN® at 1-844-436-5465.



MP1750 GeoLink GSM Precision Spray System Assembly

<i>Ref.</i>	<i>Part Number</i>	<i>Qty.</i>	<i>Description</i>	<i>Ref.</i>	<i>Part Number</i>	<i>Qty.</i>	<i>Description</i>
1	130-7306	1	Reciever	5	122-1649	1	Harness-Wire, Adapter
2	133-0410	1	Control Console ASM	6	122-1650	1	Harness-Wire, Adptr
2:1	131-3797	1	Arm-Mount, Ram ●	6:5	32180-089	1	Cap-Plug, 3 Way
2:2	130-7299	1	Base-Mount, Ram ●	7	138-6288	1	Modem CI55-Lte Aus
3	137-4258	1	Controller - Rate/Auto-Section, Asc-10	8	139-6148	1	Antenna ASM, CI55
4	122-1373	1	Harness-Wire, Geolink	9	138-6284	1	Harness - Console To Modem, CI-55
4:2	32180-043	2	Resistor-120 Ohm	10	138-6285	1	Harness - Modem To Power, CI-55
4:3	218-578	1	Fuse-Blade, 10 Amp	11	140-7310	1	Kit - Imu + Rtk Unlock
4:4	32180-019	1	Cover-Fuse, Single	11:1	130-7329	1	Module-Imu
4:5	122-1404	2	Terminator-Isobus				

● Obtain parts from Toro® NSN® at 1-844-436-5465.



Count on it.