



<b><u>Model/Serial Range:</u></b>	<b><u>Model Number:</u></b>	<b><u>Serial Numbers:</u></b>
	04051	30001-49999

Cracks may develop at the operating lever mounting holes in the handle on these units. This condition is directly related to the bouncing that occurs when the unit is transported in trailers over rough terrain. If you operate your units in this way and notice this condition on a unit listed above, the area susceptible to cracking can be strengthened. Handle Support (93-3754) is available through your local Toro distributor for this purpose. Two supports are required for each machine.

**HANDLE (88-7390)**

**CLUTCH BRACKET MOUNTING HOLES**

**USE EXISTING HARDWARE**

**BRAKE BRACKET MOUNTING HOLES**

**HANDLE SUPPORTS (93-3754) (2 REQ'D)**