



Customer Service Bulletin Commercial Business Group

Greensmaster® 3000, 3000-D, and 3100

Model/Serial Range:

Model Number:

Serial Numbers:

04350/04352

00000-99999

04353/04354/04375

00000-99999

Subject: Availability of Hydraulic Hose Replacement Kit (93-9345).

During normal operation the cutting unit hoses experience twisting, bending, high pressures and abrasion. When subjected to these stresses a hose may weaken and become a leak risk. It is important to routinely inspect for damaged hoses and replace them before a failure causes turf damage. The recommended service replacement interval for cutting unit hydraulic hoses is two years. In areas of high product usage, severe usage, or where a leak would severely impact course operations, you may wish to consider replacement of these hoses on an annual basis. Hydraulic Hose Replacement Kit (93-9345) is available to conveniently order all six cutting unit hydraulic hoses under one part number. Hydraulic Hose Servicing Manual (Form 94-813-SL) is also available and includes additional details about hose care and failure analysis. The manual and Hose Kit are available through your local Toro distributor.

