



Customer Service Bulletin Commercial Business Group

Greensmaster® 3, 300, 3000 Series

Model/Serial Range: **Model Number:** **Serial Numbers:**
ALL 00000-99999

Subject: Backlap Kit (63-4960) connectors have been improved.

Backlap Kit (63-4960) is obsolete and superseded by Backlap Kit (92-9656). The new Backlap Kit has improved Hydraulic Fittings that are more leak resistant. The improved Hydraulic Fittings (92-9658 and 92-9659) included in this kit are more positively interlocked by rotating a knurled release collar. When these fittings are disconnected, the tighter tolerance fit reduces the typical oil leakage associated with a quick disconnect feature.

The improved fittings can be installed on any traction unit equipped with the original kit but must be installed as two matched pairs (4 parts). To prevent confusion, we recommend these parts should be installed in sets of six (12 parts).

Backlap Kit (92-9656) and Hydraulic Fittings (92-9658 and 92-9659) are available through your local Toro distributor, if needed.

Note: The new style Fittings will not connect to the older Fittings, therefore both style fittings will continue to be available individually.