



## Customer Service Bulletin Commercial Business Group

### REELMASTER® 6500/6700-D

Model/Serial Range:	<u>Model Numbers:</u>	<u>Serial Numbers:</u>
	03800 / 03800TE	50101 - 70225
	03801 / 03801TE	50101 - 70233
	03802 / 03802TE	60101 - 70267

#### **Subject: Lift Arm Pivot Pin Capscrew Loosens or Backs Out**

Pivot Pin (98-3725) and Nylock Nut (3296-49) are now available for replacement purposes, which eliminates the capscrew used in the original design. The replacement Pin features a stronger retainer Tab to better resist Pin rotation and has an increased length to allow for the threads of the Nylock Nut.

The Pivot Pin and Nylock Nut combination is a direct replacement for the original Pivot Pin. During installation, tighten the Nylock Nut sufficiently to remove Pivot Pin freeplay and movement. Avoid any over-tightening that might cause binding of the lift arm in the frame.

Pivot Pin (98-3725) and Nut (3296-49) are available through your local Toro distributor.

