



Customer Service Bulletin Commercial Business Group

Reelmaster® 5100/5300/6500/6700-D

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	03502/03504	00000-99999
	03530/03530TE	40001-60527
	03531/03531TE	50001-60171
	03800/03800TE	50001-60241
	03801/03801TE	50001-60321
	03802/03802TE	60001-60283

Subject: Availability of Turf Defender™ Electronic Leak Detector Kit (03521).

The potential for hydraulic component failure exists on any hydraulically driven machine. Failures may include the loss of hydraulic fluid, which could result in turf and/or equipment damage. To minimize the damaging affects of a hydraulic leak, Turf Defender™ Electronic Leak Detector Kit (03521) is now available for installation into the units listed above. This device monitors the oil level and alerts the operator of a hydraulic fluid leak by emitting an audible alarm and turning the reels off.

Installation of an Electronic Leak Detector Kit requires activation of the software in the traction unit controller by a Toro distributor. The kit and assistance with installation are available through your local Toro distributor.

NOTE: Hydraulic Tank Update Kit (03522) is required to install an Electronic Leak Detector Kit on any machine with a serial number prior to 50999. The kit includes a replacement tank, wire harness conversion, and instructions.