



## Customer Service Bulletin Commercial Business Group

---

### Groundsmaster® 3000-D

<u>Model/Serial Range:</u>	<u>Model Numbers:</u>	<u>Serial Numbers:</u>
	30301	600001-210009999
	30301TC	00000-210009999
	30302	00000-210009999
	30302TC	00000-210009999

**Subject: Improved Fan Bracket Prevents Bracket Damage.**

The original Fan Bracket (93-5155) could crack due to vibration in some applications. Visual inspection of a damaged bracket (while the engine is running) would reveal noticeable bracket vibration at the fan bearing mounting area and degassing tank.

Orders for the Bracket will be cross-referenced to Fan Bracket Kit (104-0154). The kit includes a reinforced bracket, installation instructions and mounting hardware. Fan Bracket Kit (104-0154) is currently available from your Toro distributor. Please contact your distributor for further information about this kit.