



Customer Service Bulletin Commercial Business Group

Groundsmaster® 3500-D

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	30821	200000101-210000663

Subject: Hydraulic filter loosens during machine operation.

The original hydraulic filters provided on these units may become loose enough to leak oil. The use of a different Filter (Toro part # 86-3010) eliminates this potential condition.

Order Filter (86-3010) as a permanent replacement part. It is recommended that your parts book be changed to indicate Hydraulic Filter part number 86-3010 for future reference.

During installation, tighten the filter one complete revolution after the filter seal makes contact with the Filter Head Assembly.