



ST160 Skid/Trailer Sprayer

Model/Serial Range: Model Number: Serial Numbers:

41411 70101-80173

Subject: Quick Couplers in the pressure circuit may unlatch

The Quick Couplers used in the <u>pressure circuit</u> of the spray system do not include a positive locking device and could accidentally unlatch while the system is pressurized. If a Quick Coupler becomes unlatched, the contents of the sprayer tank will be immediately expelled to the ground and may splash onto bystanders.

A replacement Quick Coupler with Locking Latch Pins, as shown below, is available for installation at no charge through your local Toro distributor. <u>DO NOT use non-locking Quick Couplers in the pressure circuit.</u> Contact your local Toro distributor for details regarding this program.

WARNING: Failure to comply with this bulletin may lead to personal injury.



Replace this Quick Coupler, if found in the pressure circuit



Replacement Quick Coupler with Locking Latch Pins