



Topdresser 1800 & 2500

<u>Model/Serial Range:</u>	<u>Model Numbers:</u>	<u>Serial Numbers:</u>
	44225	200000101-210099999
	44507	200000101-210099999

Subject: Belt Moves Too Slow

The sand conveyer belt of the Topdresser 1800 & 2500 turn at about 25% of the Topdressers 1800/2300 produced before the listed serial numbers, this change was made in response to customer requests to provide a product that will spread very light sand applications. However, some customers may require sand distribution at higher rates than the Topdresser 1800/2500 current designs are capable of delivering.

Three alternate Sprockets are available that will enable the belt to be run 1.4, 2, or 3 times faster than the current Topdresser 1800/2500 belt speed with the 40 tooth Sprocket.

- Sprocket, 30 Tooth (1.4 times faster than current 2500 belt speed),
- Sprocket, 20 Tooth (2x faster), and,
- Sprocket, 15 Tooth (3x faster).

These sprockets are currently available through your Toro Commercial Distributor. The Drive Chain (99-0164) will need to be shortened to accommodate the use of any of these three smaller sprockets.

Sprocket Part Number	Number of Teeth on Sprocket	% Belt Speed Increase
99-0166-03	40	0
01-262-0330	30	40
01-262-0140	20	100
01-262-0040	15	200