



Customer Service Bulletin Commercial Business Group

Multi Pro® 1100

Model/Serial Range: **Model Number:** **Serial Numbers:**

41105

30101-80314

Exempt Units:

80275, 80279, 80282, 80283, 80285-80303, 80305-80309 and
80312-80314 have been corrected and are not effected by this
notice.

Subject: Improved Power Steering Cover Gasket.

The Cork material used to manufacture the original Power Steering Cover Gasket may allow excessive leaking. This can cause pooling of Power Steering Fluid along the top lip of the Power Steering Reservoir and potentially overflow down the side of the canister.

Special Limited Time Offering:

For a limited time, improved Gaskets made of a closed-cell Buna-N material are offered as a no-charge upgrade through your local Toro distributor.

If you experience this condition, you may contact your local Toro distributor for a replacement Gasket. This offer expires April 1, 1999.

The original Cork Gasket can be identified by its tan and black speckled color. The improved material is solid black in color.