



Customer Service Bulletin Commercial Business Group

Reelmaster® 5000 Series

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	03530-03531	80101-200099999
	03540-03541	80101-200099999
	03543-03544	80101-200099999

Subject: Service parts for Fan-Bearing repairs have been improved.

The service parts for the Fan-Bearing and Housing have been improved. Housing tolerances have been tightened, Spacers have an increase in mating-surface size and material strength, and the Roll Pins have been changed to solid pins. These changes were made to improve ease of service and to increase overall service life.

If repairs are performed to the Fan Bearings, use the improved Spacer (104-0001), Thrust Washer (104-9259), and Pin (104-9312). Refer to the parts diagram below for location of parts and other detail.

