




MODEL 41119

**SET-UP
&
SERVICE INFORMATION**
CONTROL VALVE SUPPORT BRACKETS
 NOTIFICATION OF CHANGE IN TORQUE SPECIFICATIONS


CAUTION: WHEN ASSEMBLING SUPPORT BRACKETS TO THE CONTROL VALVE THE ACORN AND HEX NUTS MARKED ABOVE ARE NOT TO BE TORQUED OVER 30 IN LBS (3.4NM), APPLY LOCTITE* TO THE ACORN NUTS ONLY.

OVER TORQUING MAY DISTORT THE PIPE FITTING, RESULTING IN LEAKAGE FROM THE VALVE.

TORQUE SEQUENCE
