

Greensmaster® Flex 21

Model/Serial Range: Model Number: Serial Numbers:

04021 210000101-220009999

Date: January 27, 2003

Subject: Throttle Bracket Flexes and Breaks

Control Bracket (104-9778-03) can be over-stressed if the operator repeatedly attempts to force the throttle lever beyond the maximum setting in an effort to increase engine speed.

To provide a more solid feel to the throttle and strengthen the support at the Control Bracket, Throttle Support Strap (106-8449) is now available as a product improvement. The part is available at no charge through your local Toro distributor for you to install at your convenience. Contact your local Toro distributor if you are interested in obtaining this improvement. The figure below shows the Support Strap in position. The only adjustment required is to compress the spring sufficiently to retain the throttle lever in a set position.

