



# Telematics Gateway

Model No. 161-9001

## Addendum

# Electromagnetic Compatibility Certification

**Domestic:** This device complies with FCC Rules Part 15. Operation is subject to the following two conditions: (1) This device may not cause harmful interference and (2) this device must accept any interference that may be received, including interference that may cause undesirable operation.


**FCC ID: APV-3640LB**

**IC: 5843C-3640LB**

This equipment has been tested and found to comply within the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

**Japan**



T D230055003  
R 003-230118  
001-A21797

**Morocco**

AGREE PAR L'ANRT MAROC

Numéro d'agrément: MR00004789ANRT20024  
Date d'agrément: 11/4/2024

**New Zealand**

R-NZ

**South Korea**



R-R-Tor-HMU3640LB

**United Kingdom**



**Argentina**



H-31397

**Australia**



**European Union**

