



Date: November 20, 2003

Subject: Uneven contact between reel and bedknife.

If uneven contact or a poor quality of cut is noticed, inspect for clearance between the bedbar mounting boss of the Bearing Housing and the cutting unit Side Plates. If contact is noted, a small amount of aluminum material will need to be removed from the Side Plate to eliminate the interference.

Bearing Housing

Clearance needed between aluminum side plate and outer diameter of bedbar mounting boss.