



## Customer Service Bulletin Commercial Business Group

---

**Greensmaster® 3050, 3100, 3150**


**Date: November 20, 2003**

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	04351	230000101-230009999
	04356	230000101-230009999
	04357	230000101-230009999

**Subject: Bumper (94-4548) may damage Cutting Unit Grass Shield.**

Beginning in 2003, the carrier frames were equipped with Bumper (94-4548), however their purpose was not clearly identified in the manual. These bumpers are only intended to be used with DPA Cutting Units (Model 04610 and 04611). If your greensmower is equipped with other cutting units, these bumpers must be removed or damage to the cutting unit grass shield may result. Use the illustration below as a reference.

Future Operator's Manuals (2004 and up) will be changed to include this information.



Remove Bumpers from Carrier Frames when installing Cutting Units other than Models 04610 or 04611.

Examples: 04470, 04471, 04472, 04473, 04404, 04406, 04408, 04450, and 04468.