



Customer Service Bulletin Commercial Business Group

Groundsmaster[®] 300 Series Implements Date: November 30, 2005

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	30799	200000101-220099999
	30855	200000101-250099999

Subject: Cutting Unit or Debris Blower Will Not Stay on the Ground.

Due to surplus counterbalance spring force exerted on the lift arms by the production counter balance springs these implements may lose contact with the ground in undulating conditions.

Installation of Spring – Counter Balance, LH Light (105-9550-01) will correct this issue. It is not required to change out this spring to the original Spring – Counter Balance, LH (21-2900-01) when the tractor is return to service with any of the other 300 Series attachments. The original spring does not need to be retained. Spring – Counter Balance, LH Light (105-9550-01) is currently available through Toro Commercial Product Distributors.

Please contact your local Toro Commercial Products Distributor for complete information on this issue.