



Striping Kit

72 in Side Discharge Mower for Groundsmaster® 7200/7210 Mower

Part No. 105-7273

Form No. 3356-439 Rev A

Installation Instructions

1. Remove the carriage screws and nuts securing the right and left anti-scalp rollers to the rear of the cutting unit (Fig. 1). Note the mounting position of the roller brackets.




Figure 1

1. Anti-scalp roller (2)

2. Mount the right and left striper bar mounting brackets and the previously removed anti-scalp rollers to the rear of the cutting unit with new carriage screws and nuts (Fig. 2). Note the orientation of the brackets




Figure 2

1. Left striper bar mounting bracket
2. Right striper bar mounting bracket
3. Anti-scalp roller

3. Slide the striper bar assembly under the cutting unit. From the right side of the brackets, raise the bar and slide it into the openings in the bracket (Fig. 3).




Figure 3

1. striper bar

4. Adjust the striper bar up or down to desired operating height (Fig. 4). Align the bottom of the bracket with the line on the decal which represents the cutting unit height of cut.




Figure 4

1. Operating height
2. Clevis pin
3. Ring pin

5. Secure each end of the bar to the brackets with a clevis pin and a ring pin (Fig. 4).