



Customer Service Bulletin Commercial Business Group

Groundsmaster® 3000-D 4WD

Date: March 9, 2007

<u>Model/Serial Range:</u>	<u>Model Numbers:</u>	<u>Serial Numbers:</u>
GM 3000-D	30302	60101-210000190
GM 3000-D International	30302TC	60101-230000197

Subject: 4 Wheel Drive Axle (95-2592) is Discontinued

Groundsmaster 3000-D has been out of production for some time. The rear 4-wheel drive (4WD) axle has been discontinued by the supplier. As a result, if a failure to the 4WD axle is experienced, repair parts may not be available.

A failure to Axle (95-2592) where parts are not available results in the need to convert the axle. There are two options to convert the axle.

Option 1: Remove all 4WD components and install the two wheel drive axle and steering cylinder according to Service Manual instructions. Parts are found in the parts book for the unit.

Option 2: Remove the existing 4WD axle and steering cylinder and install 4WD Rear Axle Replacement Kit (114-2860). This replacement kit utilizes a current production Daedong axle modified to run in the GM 3000-D.

Note: As a result of the different axle type, axle movement and turning radius will be slightly reduced. Most internal parts are available at the time of this publication. Repair using quality Toro parts is recommended. These alternatives are only intended for those rare instances where the parts needed are no longer available.