



Mid-mount Toolbar System Performance and Troubleshooting Guide

Product: Sand Pro/Infield Pro

April 16, 2009

Affected Units:

Models:

Serial Numbers:

Sand Pro/Infield Pro 3040

08703

All

Sand Pro/Infield Pro 5040

08705

All

Information:

A document is now available that specifically addresses the performance criteria and troubleshooting procedures for the Mid-mount Toolbar System (08731) when installed on the Sand Pro/Infield Pro 3040 and 5040 models.

Click on the following Link to access the guide:

http://extranet.thetoroco.com/secure/apps/auth_redir/auth_redir.cgi?redir_url=https://lookup3.toro.com/ttc/ComISvcDoc/?thefile=/SPECIALT/00-02 Midmount Toolbar Troubleshooting Guide.pdf

Use this new guide (along with the Mid-mount Toolbar Installation Instructions) to effectively set up the mid mount tools for maximum effective performance for your individual conditions.

If needed, contact your local authorized Toro Commercial Products distributor for additional information.