

PART NO. 93-9253

PARTS CATALOG


CE UPDATE KIT

38" Side Discharge Cutting Unit Model No. 78216

INTERNATIONAL PARTS REFERENCE EUROPEAN PARTS KIT NO. 93-9253

DESCRIPTION	DESCRIPTION LOCATION		EUROPEAN PART NO.	QTY.
Decal Belt Routing Top Side of Deck Assembly		117137	93-6679	1
Decal Deflector Danger	Top Side of Deck As- sembly		93-7009	1
Decal Danger	Top Side of Deck As- sembly	93-7110	93–7319	1
Deflector Assembly	R.H. Side of Deck As- sembly	93-0317 93-7695		1
Phillips Pan Hd. Screw	Top of Deflector Assembly		32144–111	4
Decal Danger	Top of Deflector Assembly	93-1122	93-7010	1
Kicker CE	Bottom of Deflector As- sembly		93-7696	2






DECK ASSEMBLY

Ref. No.	Part No.	Description	No. Used
1 2	93-7009 93-7319	Decal – Deflector Danger Decal – Danger	1 1

Ref. No.	Part No.	Description		
3	93-6679	Decal — Belt Routing	1	



DEFLECTOR ASSEMBLY

Ref. No.	Part No.	Description	No. Used				
1 2	93–7696 93–7695	Kicker – CE 38" Deflector Assembly	2 1				

Ref. No.	Part No.	Description	
	32144—111 93—7010	Screw — Phillips Pan Hd. Decal — Danger	4 1

PRODUCT CHANGES

In an effort to make improvements available to TORO owners as quickly as possible, minor changes are incorporated into Toro's products from time to time that do not become immediately shown in the Parts Catalog. If such a change has been made in your unit, which is not reflected in your manual, see your TORO Distributor or his Authorized TORO Service Dealer for information and part numbers.

COUNTRIES OTHER THAN THE UNITED STATES OR CANADA

Customers who have purchased TORO products exported from the United States or Canada should contact their Toro Distributor (Dealer) to obtain guarantee policies for your country, province or state. If for any reason you are dissatisfied with your Distributor's service or have difficulty obtaining guarantee information, contact the TORO importer. If all other remedies fail, you may contact us at The Toro Company.

MAINTENANCE RECORD

Date				