



Form No. 3371-635 Rev A

Count on it.


Parts Catalog

Spindle Housing Kit

TITAN Zero-Turn-Radius Riding Mower


Model No. 121-5681





Spindle Assembly

<i>Ref.</i>	<i>Part Number</i>	<i>Qty.</i>	<i>Description</i>
1	116-5138	1	Cutter Housing ASM
2	52-7280	1	Washer-Thrust



Cutter Housing Assembly No. 116-5138

Ref.	Part Number	Qty.	Description
1	116-5137	1	Housing-Cutter
1:2	116-4004	2	Bearing
1:3	116-4876	1	Spacer-Bearing
2	32144-41	6	Screw-Taptite
3	109-7431	1	Spindle-Hex Pilot
4	109-7429	1	Washer-Blade Drive
5	116-0005	1	Bolt-Blade, Sem
6	3219-6	1	Nut-Hex



Count on it.